



Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 1

Southeast Side of Maintenance Shop - (Drums from left to right, standing on north side of drums) partially full unlabeled used oil, full unlabeled used oil, full labeled used glycol, full unlabeled used oil and empty.

Dedriel Newsome

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 2

Southeast Side of Maintenance Shop - (Drums from right to left, standing on south side of drums standing in ditch) partially full unlabeled used oil, full unlabeled used oil, full labeled used glycol, full unlabeled used oil and empty. Oil stained soil showing.

Dedriel Newsome

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 3

East Side of Maintenance Shop - Used oil spill on pallet and under pallet

Dedriel Newsome





Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 4

Process Building / Nulex Warehouse - Zinc oxide in Bay #6 in super sacks -  
Sample # 007/007D

Zinc ash pile on right side of photo - Sample #005

Dedriel Newsome *DN*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 5

Process Building / Nulex Warehouse - Zinc ash in Bay #6  
Sample # 005

Dedriel Newsome *DN*


Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 6

Process Building / Nulex Warehouse - Zinc oxide in Bay #6 in super sacks  
Sample # 007

Dedriel Newsome *DN*





Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 7

Process Building / Nulex Warehouse - Zinc oxide in Bay #6 in super sacks

Sample # 007D

Dedriel Newsome *DN*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 8

Process Building / Nulex Warehouse -

in Bay #3 and Bay #5

Dedriel Newsome *DN*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 9

Process Building / Nulex Warehouse-

1 Bay #3

Sample # 001

Dedriel Newsome *DN*





Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 10

Process Building / Nulex Warehouse-

in Bay #5

Sample # 002

Dedriel Newsome

*DN*

10

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 11

Process Building / Nulex Warehouse-

in Drums east of Bays

Sample # 003

Dedriel Newsome

*DN*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 12

Process Building / Nulex Warehouse -

, in Drums east of Bays

Sample # 003

Dedriel Newsome

*DN*





Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 13

Process Building / Nulex Warehouse-

in Drums east of Bays

Sample # 003

Dedriel Newsome *[Signature]*

13

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 14

Morten Building - Zinc/iron crystals from

Sample #009 from top bag labeled .58

Dedriel Newsome *[Signature]*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 15

Morten Building - Zinc/iron crystals from

Sample #009

Dedriel Newsome *[Signature]*





Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 16

Morten Building - Zinc/iron crystals from

Sample #010 from top bag labeled .52

Dedriel Newsome *RSW*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 17

Morten Building - Zinc/iron crystals from

Sample #010

Dedriel Newsome *RSW*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98


PHOTO # 18

Morten Building - Zinc/iron crystals from

Sample #011

Dedriel Newsome *RSW*





Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO #

19

Morten Building - Zinc/iron crystals from  
Sample #011 from top front bag labeled

Dedriel Newsome

*DN*

19

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 20

Zinc/iron crystals being stored outside, west of the Granular Blending Building and southwest of the Morten Building in a concrete containment structure from a super sack on the west side.

Sample #012

Dedriel Newsome

*DN*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 21

Process Building / Nulex Warehouse (facing southeast) - Southeast exit ramp showing dust/residue from warehouse being tracked out into open.

Dedriel Newsome

*DN*







Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 22

Process Building / Nulex Warehouse (standing on east side, facing north) -  
Containers of zinc sources being stored in warehouse prior to being used in  
manufacturing process.

Dedriel Newsome

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 23

Process Building / Nulex Warehouse (standing on east side, facing northwest)  
- Containers of zinc sources being stored in warehouse prior to being used in  
manufacturing process. Dust/residue on floor in warehouse that gets tracked  
out of warehouse.

Dedriel Newsome

Nutra-Flo Company  
Sergeant Bluff, IA


9/22/98

PHOTO # 24

Process Building / Nulex Warehouse (facing west) - Drums of zinc sources  
being stored in warehouse prior to being used in manufacturing process.  
Dust/residue on floor (up to about 2 inches high) in warehouse that gets  
tracked out of warehouse. Both west and southeast doors were open at the  
time of the inspection.

Dedriel Newsome







Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 25

Process Building / Nulex Warehouse (facing west) - Dust/residue on floor (up to about 2 inches high) in warehouse that gets tracked out of warehouse. West door was open at the time of the inspection.

Dedriel Newsome *DN*

25

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 26

Process Building / Nulex Warehouse (facing east looking at west door) - Area outside of west door of warehouse. Construction was occurring in the area.

Dedriel Newsome *DN*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 27

Morten Building (standing on southeast side facing southwest) - Zinc/iron crystal storage area

Dedriel Newsome *DN*







Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 28

Morten Building (standing on southeast side facing west) - Zinc/iron crystal storage area. A spill from a tear in one of the bags had occurred.

Dedriel Newsome *DN*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 29

Morten Building (standing on southeast side facing northwest) - Zinc/iron crystal storage area. There was some (ranged up to about 2 inches high) dust/residue on the floor. This warehouse was just cleaned as was stated by one of the workers. He stated that it was just cleaned when we walked in to visually inspect.

Dedriel Newsome *DN*

Nutra-Flo Company  
Sergeant Bluff, IA


9/22/98

PHOTO # 30

Southwest Side of Facility - Drums being stored. Four unknown drums being stored. (From left to right) Drum on side-empty, empty, 1/2 full of unknown, empty and three drums that were strapped together (one labeled hydraulic oil, and other two unlabeled)

Dedriel Newsome *DN*







Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 31

Southwest Side of Facility - Drums being stored. Four unknown drums being stored. (From left to right) empty, 1/2 full of unknown, empty

Close-up of photo # 30

Dedriel Newsome

*DN*

31

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 32

Southwest Side of Facility - Drums being stored. Four unknown drums being stored. (From left to right) empty and three drums that were strapped together (one labeled hydraulic oil, and other two unlabeled). Drum on side in back, empty.

Close-up of photo # 30

Dedriel Newsome

*DN*

3

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 33

Southwest side of facility where cement trucks are cleaned out - An oil spill (about 10 ft x 35 ft). Facing northwest.

Dedriel Newsome

*DN*

33







Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 34

Southwest side of facility where cement trucks are cleaned out - An oil spill  
(about 10 ft x 35 ft). Facing west.

Dedriel Newsome *DN*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 35

Southwest side of facility where cement trucks are cleaned out - An oil spill  
(about 10 ft x 35 ft). Facing southwest.

Dedriel Newsome *DN*

Nutra-Flo Company  
Sergeant Bluff, IA

9/22/98

PHOTO # 36

Southwest side of facility where cement trucks are cleaned out - After the oil  
spill had been cleaned. Facing southeast.

Dedriel Newsome *DN*